



VEHICLE INSPECTION REPORT

PL18ZUD

Peugeot 2008 1.2 PureTech Allure 5dr [Start Stop]

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
3

Details

Reg. date	14/08/2018	Colour	WHITE	MOT Due	03/10/2026
Year	2018	VIN	VF3CUHMRPJY125090	Gearbox	MANUAL
Mileage	43,949 Miles Warranted	Body Style	Hatchback	Gears	5
Fuel Type	Petrol	Keys	2	Doors	5

£65 ADDITIONAL FEE



Tyres


NSF	ACCELERA	5.0mm
NSR	NEXEN	5.0mm
OSF	ACCELERA	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Chipped
1 To 5



3: Wheel nsf
Scratched
Over 50mm



4: Door nsr
Dented
Between 10mm + 30mm



5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Wheel osr
Corroded
Light



8: Door osr
Poor Previous Repair
Rippled UpTo 30%



9: Door osf
Chipped
1 To 5



10: Wheel osf
Scratched
Over 50mm



11: Roof
Dented
With Paint Damage

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK