



VEHICLE INSPECTION REPORT

GU23JHE

Toyota Yaris Cross 1.5 Hybrid Excel 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2023	Body Style	Hatchback	Last service miles	12,668
Year	2023	Keys	2	Gearbox	AUTOMATIC
Mileage	20,042 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Hybrid Electric	Service documents	Service Book	Doors	5
Colour	GREY	Number of stamps	2		
VIN	JTDKBBB30A180124	Last service date	11/03/2025		

£65 ADDITIONAL FEE

Last service 11/03/2025 at 12,668 miles- 2 main dealer services

Tyres

NSF	BUDGET	5.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	5.0mm
OSR	FALKEN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Bumper Rear
Scratched
Up To 25mm Thru Paint



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Door osf
Chipped
Edge Chip



9: Wing osf
Chipped
1 To 5



10: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK