

VEHICLE INSPECTION REPORT

PK67CXX

Peugeot 2008 1.2 PureTech 110 Allure 5dr EAT6

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	30/09/2017	Colour	GREEN	MOT Due	03/08/2026
Year	2017	VIN	VF3CUHNZTHY132670	Gearbox	AUTOMATIC
Mileage	34,028 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Petrol	Keys	2	Doors	5

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	6.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsr
Dented
2 Or Less UpTo 10mm



7: Door nsr
Scratched
UpTo 25mm Thru Paint



8: Wheel nsr
Corroded
Light



9: Tailgate
Scratched
Up To 25mm Thru Paint



10: Bumper Rear
Scratched
Up To 25mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Door osr
Chipped
Edge Chip



13: Door osf
Chipped
Edge Chip



14: Wing osf
Dented
Between 10mm + 30mm



15: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK