



46 Brampton Road  
Eastbourne  
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

## VEHICLE INSPECTION REPORT

**YG69FZM**

### BMW 4 Series 420d [190] xDrive M Sport 2dr Auto [Prof Media]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



#### Details

Reg. date	13/09/2019	VIN	WBA4X52070FH34106	Last service date	25/08/2025
Year	2019	Body Style	Coupe	Last service miles	54,271
Mileage	58,814 Miles Warranted	Keys	2	MOT Due	12/09/2026
Fuel Type	Diesel	Service history	Yes	Gearbox	AUTOMATIC
Colour	GREY	Number of stamps	3	Gears	8

£100 ADDITIONAL FEE. Services stored in on-board system.  
Mileage of last service recorded incorrectly on on-board system.  
Last service 25/08/2025 at 54271 miles (3 services).

#### Tyres

NSF	MICHELIN	4.0mm
NSR	MICHELIN	2.0mm
OSF	MICHELIN	Damaged
OSR	MICHELIN	2.0mm
Spare		

## Features

- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Body coloured bumpers
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos










## Condition Check



## Damage Photos



1: Wheel osf  
Scratched  
Over 50mm



2: Wheel nsf  
Scratched  
Over 50mm





3: Wheel nsr  
Scratched  
Over 50mm



4: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



5: Door osf  
Chipped  
Edge Chip



6: Qtr Panel osr  
Chipped  
1 To 5



7: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



8: Bumper Front  
Chipped  
Multiple Chips






9: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



10: Bonnet  
Chipped  
1 To 5



11: Tyre osf  
Damaged  
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK



EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK