

46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

FA17SFY

Skoda Superb 2.0 TSI SE L Executive 5dr DSG

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	ТВС		
Details					
Reg. date	25/08/2017	Body Style	Hatchback	CAP Clean	£12,150.00
Year	2017	Keys	3	CAP Average	£11,050.00
Mileage	28,916 Miles Warranted	Number of stamps	4	CAP Below	£9,950.00
		Last service date	20/09/2024	Gearbox	SEMI AUTO
Fuel Type	Petrol	Last service miles	25,272	Gears	6
Colour	BLACK	MOT Due	21/09/2025	Doors	5
VIN	TMBBD7NP2J7510421				-

Last Service - 20.09.2024 at 25272 miles (4 services)

Tyres			
NSF	BUDGET	5.0mm	
NSR	AVON	6.0mm	
OSF	BUDGET	6.0mm	
OSR	AVON	6.0mm	
Spare			

Features

Cruise control

- Bluetooth connection
- PAS
 Body coloured bumpers
 Electrically adjustable drivers seat
 Rear headrests
 ESP
 Central locking
 Alloy wheels
 Cruise control
 Rear parking sensor
 Electric door mirrors
 Metallic Paint
 Passenger airbag
 Remote central locking

- Metallic Paint
 Passenger airbag
 Remote central locking
- Heated front seatTelephone

- Air conditioningFront electric windows
- ABSTraction control
- · Cloth seat trim
- Navigation systemRadio/CD
- Climate control
- Rear electric windows
- Drivers airbag
 Tyre pressure monitor
- Leather seat trim

Photos










Condition Check



Damage Photos



1: Wing osf Scratched Over 25mm Not Thru Paint



2: Door osf Scratched Over 25mm Not Thru Paint



3: Bumper Rear Scratched 25 to 100mm Thru Paint



5: Bumper Front Scratched 25 to 100mm Thru Paint



4: Wing nsf Scratched Over 25mm Not Thru Paint



6: Wheel osf Scratched Over 50mm



7: Wheel nsr Scratched Over 50mm



8: Wheel nsf Scratched Over 50mm

Interior

Eastbourne Car Auctions

Carpet Condition	ОК	Upholstery Condition	OK
Seat Condition	OK	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
	OK	Steering	OK