



VEHICLE INSPECTION REPORT

SA18KKD

Ford Fiesta 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
3

Details

Reg. date	28/03/2018	VIN	WF0JXXGAHJHD88367	CAP Average	£4,725.00
Year	2018	Body Style	Hatchback	CAP Below	£3,975.00
Mileage	63,547 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	27/03/2026	Gears	6
Colour	BLUE	CAP Clean	£5,475.00	Doors	5



£65 ADDITIONAL FEE. Engine noisy

Tyres		
NSF	BUDGET	3.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Side airbags
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Air conditioning
- Height adjustable drivers seat
- ABS
- Traction control
- Alloy wheels
- Navigation system
- Telephone
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Trip computer
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Dented
Over 30mm



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
Multiple Chips



6: Door nsr
Dented
2 Or Less UpTo 10mm



7: Wheel nsr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Wheel osr
Scratched
Over 50mm



10: Qtr Panel osr
Chipped
1 To 5



11: Door osr
Chipped
1 To 5



12: Door osf
Chipped
1 To 5



13: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Turbo Boosting	OK	Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK