



VEHICLE INSPECTION REPORT

HJ66ZNE

Nissan X-Trail 1.6 DiG-T Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
2

Details

Reg. date	01/12/2016	VIN	JN1TDAT32U0005415	CAP Average	£5,675.00
Year	2016	Body Style	Estate	CAP Below	£4,800.00
Mileage	108,348 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	17/10/2025	Gears	6
Colour	GREY	CAP Clean	£6,525.00		

£100 ADDITIONAL FEE. Noisy engine

Tyres		
NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Trip computer
- Body coloured bumpers
- Climate control
- Cruise control
- Park assist camera
- Service indicator
- Audio remote control
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Leather seat trim
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Telephone
- Digital radio
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Remote central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Chipped
1 To 5



6: Door nsr
Chipped
1 To 5



7: Wheel nsr
Scratched
Up To 50mm




8: Bumper Rear
Chipped
Multiple Chips



9: Wheel osr
Scratched
Up To 50mm

10: Door osr
Chipped
1 To 5



11: Door osf
Chipped
1 To 5

12: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		