



# VEHICLE INSPECTION REPORT

**GV67PJJ**

## Kia Stonic 1.0T GDi First Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	31/01/2018	Keys	2	CAP Clean	£7,850.00
Year	2018	Service history	Yes	CAP Average	£6,825.00
Mileage	55,533 Miles Warranted	Service documents	Service Book	CAP Below	£5,800.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	RED	Last service date	18/09/2024	Gears	6
VIN	KNAD6811LJ6083871	Last service miles	51,326	Doors	5
Body Style	Hatchback	MOT Due	22/09/2025		

Last Service - 18.09.2024 at 51326 miles (7 services) Vibration while revving

### Tyres

NSF	KUMHO	4.0mm
NSR	OVATION	3.0mm
OSF	KUMHO	5.0mm
OSR	OVATION	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Telephone
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- PAS
- Trip computer
- Body coloured bumpers
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint





3: Wheel nsf  
Scratched  
Over 50mm



4: Door nsr  
Chipped  
1 To 5



5: Door nsf  
Dented  
Between 10mm + 30mm



6: Wheel nsr  
Scratched  
Over 50mm



7: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



8: Door osr  
Chipped  
1 To 5



9: Wheel osf  
Scratched  
Over 50mm



10: Door osf  
Dented  
Over 2 UpTo 10mm



11: Wing osf  
Dented  
Over 2 UpTo 10mm



12: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition** OK  
**Seat Condition** OK

**Upholstery Condition** OK  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK