



46 Brampton Road
Eastbourne
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

DN22WXB

Hyundai Kona 1.0 TGD i 48V MHEV SE Connect 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
2

Details

Reg. date	17/06/2022	VIN	KMHK2812LNU899167	CAP Average	£10,600.00
Year	2022	Body Style	Hatchback	CAP Below	£9,425.00
Mileage	28,791 Miles Warranted	Keys	1	Gearbox	MANUAL
Fuel Type	Hybrid Electric	MOT Due	16/06/2025	Gears	6
Colour	BLACK	CAP Clean	£11,750.00	Doors	5

£100 ADDITIONAL FEE.


Tyres

NSF	NEXEN	2.0mm
NSR	NEXEN	4.0mm
OSF	NEXEN	2.0mm
OSR	NEXEN	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front head restraints
- Solid Paint
- Passenger airbag
- Remote central locking
- Park assist camera
- Telephone
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Cloth seat trim
- PAS
- Trip computer
- Body coloured bumpers
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Up To 50mm




4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
With Paint Damage




6: Door nsr
Dented
Between 10mm + 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Boot Lid
Chipped
1 To 5



9: Wheel osr
Scratched
Up To 50mm

10: Door osr
Scratched
Over 25mm Not Thru Paint



11: Door osf
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK