



VEHICLE INSPECTION REPORT

GU58RKO

Ford Fiesta 1.25 Zetec 3dr [Climate]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
3

Details

Reg. date	17/09/2008	VIN	WF0DXXGAJD8G10195	CAP Average	£200.00
Year	2008	Body Style	Hatchback	CAP Below	£200.00
Mileage	95,856 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	20/09/2025	Gears	5
Colour	BLACK	CAP Clean	£450.00	Doors	3

Clutch Slipping

Tyres		
NSF	BUDGET	5.0mm
NSR	BUDGET	2.3mm
OSF	SUNNY	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Rear wiper
- Electric door mirrors
- Metallic Paint
- Central locking
- Telephone
- Air conditioning
- ABS
- Cloth seat trim
- Radio/CD
- Front electric windows
- Drivers airbag
- Alloy wheels
- Body coloured bumpers
- Rear headrests
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Wing of
Dented
2 Or Less Up To 10mm



2: Door Moulding of
Scratched (Painted)
Up To 25mm Thru Paint



3: Qtr Panel osr
Chipped
1 To 5



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Door nsf
Chipped
Multiple Chips



7: Other
N/A
N/A



8: Bonnet
Chipped
1 To 5



9: Wheel osf
Scratched
Over 50mm



10: Wheel osr
Scratched
Over 50mm



11: Wheel nsr
Scratched
Over 50mm



12: Wheel nsf
Scratched
Over 50mm



13: Badgedecal Front
Missing
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK