

## VEHICLE INSPECTION REPORT

**MJ62KWA**

### RENAULT TRAFIC SL27dCi 115 [Sat Nav] Van Euro 5

Inspection	Vehicle	nama GRADE 4
Serious Damage?	VAT	Margin
No	V5	Present

#### Details

Reg. date	14/11/2012	VIN	VF1FLA1AEDV436085	Last service date	11/09/2024
Year	2012	Body Style	Panel Van	Last service miles	176,797
Mileage	180,177 Miles Warranted	Service history	Yes	MOT Due	10/09/2026
Fuel Type	Diesel	Service documents	Printout	Gearbox	MANUAL
Colour	WHITE	Number of stamps	5	Gears	6

Last service 11/09/2024 at 176797 miles (5 services). Clutch pedal sticks and injection fault  
Eml on and service light on  
Radio insecure and entertainment screen broken  
Van has been plugged in and detects turbo/supercharger underboost also detects diesel particulate filter  
restriction and also engine oil deteriorated

#### Tyres


NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

#### Photos





## Condition Check



## Damage Photos



1: Boot Lid  
Rusted  
Over 5mm



2: Qtr Panel osr  
Dented  
With Paint Damage



3: Door osf  
Chipped  
Multiple Chips



4: Wing osf  
Dented  
With Paint Damage




5: Bumper Front  
Scratched  
Over 100mm Thru Paint



6: Bonnet  
Chipped  
Multiple Chips



7: Wing nsf  
Dented  
Over 2 UpTo 10mm



8: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



9: Door nsf  
Chipped  
Multiple Chips



10: Other  
N/A  
N/A




11: Door nsr  
Dented  
With Paint Damage



12: Qtr Panel nsr  
Dented  
With Paint Damage



13: Roof  
Dented  
Over 30mm



14: Seat Base Cover osf  
Torn  
Over 3mm



15: Air Vents osf  
Damaged  
Replace

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Poor	<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	Fault
		Steering	OK