

## **VEHICLE INSPECTION REPORT**

SJ17POV

## Nissan Qashqai 1.2 DiG-T Tekna [Non-Panoramic] 5dr

Inspection		Vehicle		nama
No	VAT	Margin		Grad Grad
	V5	Present		
11/04/2017	Keys	2	CAP Average	£5,575.00
2017	Service history	Yes	CAP Below	£4,775.00
54,682 Miles	Service documents	Printout	Gearbox	MANUAL
Warranted	Number of stamps	6	Gears	6
Petrol	Last service date	22/01/2024	Doors	5
BLUE	MOT Due	18/11/2025		
SJNFEAJ11U1866505	CAP Clean	£6.400.00		
Hatchback		,		
	11/04/2017 2017 54,682 Miles Warranted Petrol BLUE SJNFEAJ11U1866505	No VAT V5  11/04/2017 Keys 2017 Service history 54,682 Miles Warranted Survice documents Petrol Last service date BLUE MOT Due CAP Clean	No         VAT         Margin           V5         Present           11/04/2017         Keys         2           2017         Service history         Yes           54,682 Miles         Service documents         Printout           Number of stamps         6           Petrol         Last service date         22/01/2024           BLUE         MOT Due         18/11/2025           SJNFEAJ11U1866505         CAP Clean         £6,400.00	No         VAT         Margin           V5         Present           11/04/2017         Keys         2         CAP Average           2017         Service history         Yes         CAP Below           54,682 Miles         Service documents         Printout         Gearbox           Warranted         Number of stamps         6         Gears           Petrol         Last service date         22/01/2024         Doors           BLUE         MOT Due         18/11/2025           SJNFEAJ11U1866505         CAP Clean         £6,400.00

Last Service - 22.01.2024 at unknown miles (6 services) Clutch Replaced 19.02.2025 Car is knocking from front when driving

### **Tyres**

NSF	SUNNY	5.0mm	
NSR	BUDGET	6.0mm	
OSF	BUDGET	4.0mm	
OSR	SUNNY	6.0mm	
Spare			

### **Features**

- Bluetooth connection
- · Park assist camera
- TelephoneFixed panoramic glass roof
- Front armrest
- Metallic Paint
- Passenger airbagRemote central locking
- Cruise control
- PAS
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Traction control
- Leather seat trim

- Front parking sensor
   Rear parking sensor
   Body coloured bumpers
   Climate control
   Rear electric windows
   Drivers airbag

- Drivers airbag Tyre pressure monitor Alloy wheels


- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrestsESP
- Central locking

### **Photos**










# **Condition Check**



## **Damage Photos**



1: Wheel osf Scratched Over 50mm



2: Wheel osr Scratched Over 50mm



3: Wheel nsr Scratched Over 50mm



4: Wheel nsf Scratched Over 50mm



5: Door osf Scratched Over 25mm Thru Paint



6: Door osr Scratched Over 25mm Thru Paint



7: Qtr Panel nsr Chipped 1 To 5



8: Bumper Rear Poor Previous Repair Poor Paint



9: Qtr Panel nsr Chipped 1 To 5

### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

## **Vehicle Inspection Report**

#### Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		