



VEHICLE INSPECTION REPORT

WR68LNP

Ford Focus 1.0 EcoBoost 125 ST-Line X 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	31/10/2018	VIN	WF0NXXGCHNJJ54907	CAP Below	£6,900.00
Year	2018	Body Style	Hatchback	Gearbox	MANUAL
Mileage	65,693 Miles Warranted	MOT Due	30/07/2025	Gears	6
Fuel Type	Petrol	CAP Clean	£8,925.00	Doors	5
Colour	GREY	CAP Average	£7,925.00		

£65 ADDITIONAL FEE

Tyres

NSF	FALKEN	3.0mm
NSR	FALKEN	3.0mm
OSF	FALKEN	2.0mm
OSR	FALKEN	2.0mm
Spare		


Features

- Bluetooth connection
- PAS
- Telephone
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Passenger airbag
- Central locking
- Cruise control
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Remote central locking
- Front parking sensor
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Partial leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos



Condition Check



Damage Photos



1: Screen Front
Chipped
UpTo 10mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
Multiple Chips



4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Chipped
1 To 5



7: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



8: Wheel nsr
Corroded
Light



9: Bumper Rear
Chipped
Multiple Chips




10: Qtr Panel osr
Chipped
1 To 5



11: Wheel osr
Scratched
Up To 50mm



12: Door osf
Chipped
Edge Chip



13: Door osf
Scratched
Over 25mm Not Thru Paint



14: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK