



VEHICLE INSPECTION REPORT

DE62CPV

Volkswagen Polo 1.4 Match 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	01/11/2012	VIN	WVWZZZ6RZDU003113	CAP Average	£3,350.00
Year	2012	Body Style	Hatchback	CAP Below	£2,725.00
Mileage	74,673 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	31/10/2025	Gears	5
Colour	GREY	CAP Clean	£3,950.00	Doors	5

£65 ADDITIONAL FEE


Tyres

NSF
NSR
OSF
OSR
Spare

Features

- | | | | |
|---|--|--|--|
| <ul style="list-style-type: none">• Rear wiper• Air conditioning• Metallic Paint• Traction control• Cloth seat trim | <ul style="list-style-type: none">• Radio/CD• Front electric windows• ABS• Tyre pressure monitor• Alloy wheels | <ul style="list-style-type: none">• Body coloured bumpers• Rear electric windows• Drivers airbag• Central locking | <ul style="list-style-type: none">• Electric door mirrors• Rear headrests• Passenger airbag• Remote central locking |
|---|--|--|--|

Condition Check



Damage Photos

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows

OK

Radio

OK

Steering

OK