

# **VEHICLE INSPECTION REPORT**

# SM61KHU

# Mini Coupe 1.6 John Cooper Works 3dr

inspection		venicie			nama
Serious Damage?	No	VAT	Margin		2 crape
		V5	Present		
Details					
Reg. date	23/11/2011	Body Style	Coupe	Last service miles	45,550
Year	2011	Keys	2	MOT Due	30/01/2026
Mileage	47,252 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	11		
VIN	WMWSX52050T287734	Last service date	17/02/2025		

Last Service - 17.02.2025 at 45550 miles (11 services)

Tν	res
----	-----

NSF	MICHELIN	4.0mm	
NSR	MICHELIN	4.0mm	
OSF	MICHELIN	4.0mm	
OSR	MICHELIN	4.0mm	
Spare			

### **Features**

- Bluetooth connection
- Radio/CD
- Climate control
- ABSTyre pressure monitor
- Leather seat trim
- Heated front seat
- Body coloured bumpers
- Front armrest Drivers airbag
- Central locking
- Alloy wheels
- · Navigation system
- Electric door mirrors
- Front electric windows
- Passenger airbag Remote central locking
- Telephone
- Air conditioning
- Solid Paint Traction control
- Cloth seat trim

### **Photos**























# **Condition Check**



## **Damage Photos**



1: Wheel osf Scratched Over 50mm




2: Door osf Chipped Edge Chip



3: Bumper Front Chipped 1 To 5



4: Bonnet Chipped Multiple Chips



5: Screen Front Chipped UpTo 10mm

### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

### **Vehicle Inspection Report**

#### **Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	ОК
Sat nav	OK	Steering	OK