



VEHICLE INSPECTION REPORT

LL17TVE

Ford Ranger Pick Up Double Cab Wildtrak 3.2 TDCi 200 Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

Details

Reg. date	24/06/2017	VIN	6FPPXXMJ2PHM51835	CAP Below	£7,575.00
Year	2017	Body Style	Pick-up	Gearbox	AUTOMATIC
Mileage	63,107 Miles Warranted	MOT Due	01/01/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£11,750.00		
Colour	ORANGE	CAP Average	£9,975.00		

£100 ADDITIONAL FEE Eml on

Tyres



NSF	GOODYEAR	6.0mm
NSR	GOODYEAR	6.0mm
OSF	GOODYEAR	6.0mm
OSR	GOODYEAR	6.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Digital radio
- Metallic Paint
- Partial leather seat trim
- Cruise control
- Park assist camera
- Air conditioning
- Drivers airbag
- Front parking sensor
- Rear parking sensor
- Front electric windows
- Passenger airbag
- Heated front seat
- Auxiliary input socket
- Rear electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Corroded
Light



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Chipped
1 To 5



9: Boot Lid
Dented
With Paint Damage



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Qtr Panel osr
Chipped
1 To 5



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Chipped
1 To 5



14: Wing osf
Chipped
1 To 5

No Image



15: Door osf
Scratched
Over 25mm Not Thru Paint

16: Wheel osf
Scratched
Over 50mm



17: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK