



VEHICLE INSPECTION REPORT

YN19HGH

Mini Hatchback 2.0 John Cooper Works II 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/06/2019	VIN	WMWXR920602L10337	CAP Average	£12,600.00
Year	2019	Body Style	Hatchback	CAP Below	£11,500.00
Mileage	26,537 Miles Warranted	Keys	1	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	25/06/2025	Gears	6
Colour	RED	CAP Clean	£13,700.00	Doors	3

Intermittent vibration

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	DUNLOP	4.0mm
OSR	PIRELLI	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Telephone
- Digital radio
- Climate control
- Height adjustable drivers seat
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Central locking
- Front parking sensor
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Steering wheel mounted controls
- Auxiliary input socket
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 25mm Not Thru Paint



2: Wheel nsr
Scratched
Over 50mm

No Image



3: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint


4: Door nsf
Dented
Over 2 UpTo 10mm



5: Wing nsf
Chipped
1 To 5



6: Wheel nsf
Scratched
Over 50mm



7: Bonnet
Chipped
1 To 5



8: Screen Front
Chipped
UpTo 10mm



9: Bumper Front
Scratched
25 to 100mm Thru Paint



10: Wheel osf
Scratched
Over 50mm



11: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



12: Wheel osr
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK