

VEHICLE INSPECTION REPORT

GX71XCN

Audi Q3 40 TFSI Quattro Black Edition 5dr S Tronic

Inspection	Vehicle		GRADE 2
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	23/12/2021	Body Style	Estate	Last service miles	26,051
Year	2021	Keys	2	MOT Due	14/01/2027
Mileage	33,560 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Petrol	Service documents	Printout	Gears	7
Colour	GREY	Number of stamps	2		
VIN	WAUZZZ34N1062373	Last service date	27/12/2024		

£65 ADDITIONAL FEE.

Last service 27/12/2024 at 26051 miles (2 services).

Comfort and sound pack


Tyres			
NSF	BUDGET		5.0mm
NSR	RAPID		5.0mm
OSF	BUDGET		5.0mm
OSR	RAPID		5.0mm
Spare			

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image


3: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Up To 50mm

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
1 To 5

No Image

7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Chipped
1 To 5

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Up To 50mm



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

12: Bumper Rear
Chipped
Multiple Chips

No Image

No Image

13: Bumper Rear
Scratched
Over 25mm Not Thru Paint

14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



16: Wheel osr
Scratched
Up To 50mm




17: Qtr Panel osr
Dented
Between 10mm + 30mm



18: Door osr
Chipped
1 To 5



19: Door osf
Chipped
1 To 5



20: Door osf
Scratched
Over 25mm Not Thru Paint

No Image



21: Wing osf
Scratched
Over 25mm Not Thru Paint

22: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK