



VEHICLE INSPECTION REPORT

AV18FJN

Fiat 500 1.2 Lounge 3dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
2

Details

Reg. date	30/03/2018	Body Style	Hatchback	Last service miles	62,332
Year	2018	Keys	2	MOT Due	04/12/2026
Mileage	67,149 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	PINK	Number of stamps	5	Doors	3
VIN	ZFA3120000J938556	Last service date	06/12/2024		

Last service 06/12/2024 at 62,332 miles- 5 services (4 main dealer) Book

Tyres

NSF	COMFORSER	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	COMFORSER	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Rear airbags
- Cloth seat trim
- PAS
- Digital radio
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Chipped
1 To 5




3: Wing osf
Chipped
1 To 5




4: Door nsf
Scratched
UpTo 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Scratched
Up To 25mm Thru Paint



7: Door osf
Dented
Between 10mm + 30mm



8: Wing osf
Chipped
1 To 5



9: Wheel osf
Scratched
Over 50mm



10: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK