

VEHICLE INSPECTION REPORT

LM70XRB

Audi A5 40 TDI S Line 5dr S Tronic

Inspection	Vehicle		GRADE nama 3
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	27/10/2020	Body Style	Hatchback	Last service miles	47,271
Year	2020	Keys	2	MOT Due	10/07/2026
Mileage	49,837 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Printout	Gears	7
Colour	BLACK	Number of stamps	1	Doors	5
VIN	WAUZZZP53KA085740	Last service date	13/06/2025		

£65 ADDITIONAL FEE

Last Service - 13.06.2025 at 47271 miles (1 main dealer services)

Car has been plugged in and detects cylinder 3 glow plug circuit

Tyres


NSF	KUMHO	5.0mm
NSR	KUMHO	5.0mm
OSF	KUMHO	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Front parking sensor	• Heated front seat
• Navigation system	• PAS	• Rear parking sensor	• Steering wheel mounted controls
• Digital radio	• Body coloured bumpers	• Electric door mirrors	• Front fog lights
• Towbar	• Air conditioning	• Folding rear seats	• Front armrest
• Front electric windows	• Front head restraints	• Height adjustable drivers seat	• Rear electric windows
• Rear headrests	• Steering wheel rake adjustment	• Steering wheel reach adjustment	• Metallic Paint
• 3x3 point rear seat belts	• ABS	• Drivers airbag	• ESP
• Isofix child seat anchor points	• Passenger airbag	• Side airbags	• Central locking
• Remote central locking	• Partial leather seat trim	• Alloy wheels	

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Between 10mm + 30mm



6: Wheel nsr
Scratched
Up To 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Door osf
Dented
Over 30mm



9: Wheel osf
Scratched
Over 50mm



10: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK