

VEHICLE INSPECTION REPORT

VU73HTN

Vauxhall Astra 1.2 Turbo 130 GS 5dr

Inspection	Vehicle		GRADE 2
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	29/02/2024	Body Style	Hatchback	Last service miles	10,544
Year	2024	Keys	2	MOT Due	28/02/2027
Mileage	10,931 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	2	Doors	5
VIN	VXKFPNNSLR1002924	Last service date	27/10/2025		

£65 ADDITIONAL FEE.

Last Service - 27.10.2025 at 10544 miles (2 main dealer services)

Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Partial leather seat trim
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Front
Chipped
1 To 5



2: Wheel nsf
Scratched
Up To 50mm



3: Door nsf
Dented
Between 10mm + 30mm



4: Wheel nsr
Scratched
Up To 50mm



5: Wheel osr
Scratched
Up To 50mm



6: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK