

VEHICLE INSPECTION REPORT

KN16GKX

Renault Trafic SL27dCi 115 Business+ Van

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	31/03/2016
Year	2016
Mileage	157,429 Miles Warranted
Fuel Type	Diesel
Colour	WHITE
VIN	VF13FL00254851047

Body Style	Panel Van
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	5
Last service date	12/05/2023

Last service miles	118,515
MOT Due	28/05/2026
Gearbox	MANUAL
Gears	6

Last service 12/05/2023 at 118,515 miles- 5 services. Print
Mileage not recorded for service in 2021 Drivers window fault and tapping engine


Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Air conditioning
- Cloth seat trim
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Handle Inner osf
Damaged
Replace



2: Seat Base Cover osf
Torn
Over 3mm



3: Carpets Front
Torn
Over 10mm



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Wing nsf
Poor Previous Repair
Poor Paint



7: Door Mirror Glass ns
Broken
Replace



8: Door nsf
Chipped
Multiple Chips



9: Door Moulding nsf
Missing
Replace

10: Door nsr
Dented
With Paint Damage



11: Qtr Panel nsr
Dented
With Paint Damage

12: Boot Lid
Dented
With Paint Damage



13: Bumper Rear
Scratched
25 to 100mm Thru Paint

14: Roof
Dented
Over 30mm



15: Bumper Rear
Scratched
25 to 100mm Thru Paint



16: Qtr Panel osr
Dented
With Paint Damage



17: Door osf
Dented
With Paint Damage



18: Door Mirror Assy osf
Broken
Replace



19: Door Mirror Glass os
Broken
Replace



20: Wing osf
Dented
With Paint Damage

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	Fault	Radio	OK
		Steering	OK