

VEHICLE INSPECTION REPORT

ND61FZA

Volkswagen Polo 1.2 60 Match 3dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	30/11/2011
Year	2011
Mileage	106,588 Miles Warranted
Fuel Type	Petrol
Colour	WHITE
VIN	WVWZZZ6RZCY104244

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	11
Last service date	10/09/2025

Last service miles	104,343
MOT Due	05/10/2026
Gearbox	MANUAL
Gears	5
Doors	3

£65 ADDITIONAL FEE.

Last service 10/09/2025 at 104,343 miles- 11 services (2 main dealer) Book and print Noisy idle

Tyres

NSF	LAUFENN	3.0mm
NSR	LAUFENN	3.0mm
OSF	LAUFENN	3.0mm
OSR	LAUFENN	3.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Other

N/A

N/A



2: Carpets Front

Torn


Over 10mm



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front
Chipped
Multiple Chips



5: Bumper Front
Scratched
Over 25mm Not Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Chipped
1 To 5



8: Door nsf
Dented
With Paint Damage



9: Qtr Panel nsr
Poor Previous Repair
Poor Paint



10: Sill ns
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Dented
With Paint Damage



13: Boot Lid
Dented
Over 2 UpTo 10mm



14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



15: Wheel osr
Scratched
Over 50mm



16: Door osf
Chipped
Multiple Chips



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Over 50mm



19: Screen Front
Chipped
UpTo 10mm



20: Headlamp os
Broken
Replace

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK