



# VEHICLE INSPECTION REPORT

CA19JXC

## Dacia Duster JOURNEY DCI

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	27/03/2019	Keys	2	CAP Clean	£10,500.00
Year	2019	Service history	Yes	CAP Average	£9,350.00
Mileage	63,705 Miles Warranted	Service documents	Printout	CAP Below	£8,225.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	Manual
Colour	BEIGE	Last service date	14/03/2023	Doors	5
VIN	VF1HJD20262479201	Last service miles	4		
Body Style	Hatchback	MOT Due	07/04/2026		

Last Service: 14/03/2023 at 61371 miles. (4 main dealer services ) EML light on  
Spanner light on

### Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	6.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	6.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Cloth seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Alloy wheels
- Park assist camera
- Radio/CD
- Front armrest
- Metallic Paint
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Door osf  
Chipped  
Edge Chip



2: Bumper Rear  
Scratched  
25 to 100mm Thru Paint





3: Wheel nsr  
Scratched  
Over 50mm

4:

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK