

VEHICLE INSPECTION REPORT

RV69FHC

Peugeot Expert 1200 1.5 BlueHDI 100 Professional Van

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	TBC

nama
GRADE 4

Details

Reg. date	11/10/2019
Year	2019
Mileage	120,448 Miles Warranted
Fuel Type	Diesel

Colour	GREY
VIN	VF3VBYHRKKZ074427
Body Style	Panel Van
Keys	3

MOT Due	10/10/2026
Gearbox	MANUAL
Gears	6

Only two keys work

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Air conditioning
- Central locking
- Cruise control
- Front electric windows
- Partial leather seat trim
- Rear parking sensor
- Metallic Paint
- Digital radio
- Drivers airbag

Photos





Condition Check



Damage Photos



1: Boot Lid
Dented
Over 30mm



2: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Qtr Panel osr
Dented
Over 30mm



4: Door osr
Dented
Over 30mm




5: Door Moulding osf
Missing
Replace



6: Door osf
Dented
Over 30mm



7: Wing osf
Chipped
1 To 5



8: Wing osf
Scratched
Over 25mm Not Thru Paint



9: Bumper Front
Chipped
Multiple Chips

No Image

10: Bumper Front
Scratched
Over 25mm Not Thru Paint



11: Bonnet
Chipped
1 To 5



12: Bumper Front
Scratched
25 to 100mm Thru Paint



13: Wing nsf
Dented
With Paint Damage



14: Door nsf
Dented
Over 30mm



15: Door Moulding nsr
Missing
Replace




16: Door nsr
Dented
With Paint Damage



17: Sill ns
Dented
With Paint Damage



18: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



19: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



20: Roof
Dented
Over 30mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK