

## VEHICLE INSPECTION REPORT

RV69FGP

### Peugeot Partner 950 1.5 BlueHDI 100 Professional Van

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Plus VAT
V5	TBC

nama  
GRADE 3

#### Details

Reg. date	18/09/2019
Year	2019
Mileage	58,774 Miles Warranted
Fuel Type	Diesel

Colour	GREY
VIN	VR3EFYHYCKJ754945
Body Style	Panel Van
Keys	2

MOT Due	23/09/2026
Gearbox	MANUAL
Gears	5

#### Tyres


NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cloth seat trim

## Photos





## Condition Check




## Damage Photos



1: Boot Lid  
Dented  
With Paint Damage




2: Bumper Rear Moulding  
Scuffed (Unpainted)  
Over 100mm



3: Qtr Panel osr  
Dented  
Over 30mm




4: Door osr  
Dented  
Over 2 UpTo 10mm



5: Door osr  
Scratched  
Over 25mm Not Thru Paint



6: Door osf  
Chipped  
1 To 5



7: Door osf  
Scratched  
Over 25mm Not Thru Paint



8: Wing osf  
Chipped  
1 To 5



9: Roof  
Dented  
Over 30mm



10: Bonnet  
Chipped  
1 To 5




11: Bumper Front  
Scratched  
25 to 100mm Thru Paint

No Image

12: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



13: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



14: Door nsf  
Dented  
Over 2 UpTo 10mm

# No Image

15: Door nsf  
Scratched  
UpTo 25mm Not Thru Paint



16: Door nsf  
Poor Previous Repair  
Poor Paint

17: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint

## Interior

<b>Carpet Condition</b>	Average	<b>Upholstery Condition</b>	Average
<b>Seat Condition</b>	Average	<b>Odour</b>	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK