

## VEHICLE INSPECTION REPORT

KR17UUW

### Audi A5 S5 Quattro 5dr Tiptronic

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 2

#### Details

Reg. date	15/06/2017
Year	2017
Mileage	45,563 Miles Warranted
Fuel Type	Petrol
Colour	BLUE
VIN	WAUZZZF56HA037755

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	9
Last service date	16/09/2025

MOT Due	13/08/2026
Gearbox	AUTOMATIC
Gears	8
Doors	5

Last Service - 16.09.2025 at unknown miles (9 services)

HOST ALARM FITTED Car is fitted with ghost alarm

Engine tapping

#### Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


• Bluetooth connection	• Cruise control	• Front parking sensor	• Heated front seat
• Navigation system	• PAS	• Rear parking sensor	• Steering wheel mounted controls
• Audio remote control	• Digital radio	• Body coloured bumpers	• Electric door mirrors
• Air conditioning	• Climate control	• Electrically adjustable drivers seat	• Electrically adjustable passenger seat
• Front armrest	• Front electric windows	• Front head restraints	• Height adjustable drivers seat
• Rear armrest	• Rear electric windows	• Rear headrests	• Metallic Paint
• 3x3 point rear seat belts	• ABS	• Drivers airbag	• Isofix child seat anchor points
• Passenger airbag	• Side airbags	• Traction control	• Central locking
• Remote central locking	• Leather seat trim	• Alloy wheels	

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint

# No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wing nsf  
Chipped  
1 To 5



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Chipped  
1 To 5

# No Image

7: Door nsf  
Scratched  
Over 25mm Not Thru Paint




8: Door nsr  
Chipped  
1 To 5



9: Door nsr  
Dented  
2 Or Less UpTo 10mm



10: Qtr Panel nsr  
Chipped  
1 To 5




11: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



12: Wheel nsr  
Scratched  
Over 50mm



13: Bumper Rear  
Chipped  
Multiple Chips



14: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

# No Image

15: Boot Lid  
Chipped  
1 To 5



16: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



17: Wheel osr  
Scratched  
Up To 50mm



18: Door osr  
Chipped  
1 To 5

# No Image

19: Door osr  
Scratched  
Over 25mm Not Thru Paint



20: Door osf  
Poor Previous Repair  
Poor Paint



21: Wing osf  
Chipped  
1 To 5

No Image

22: Wing osf  
Scratched  
Over 25mm Not Thru Paint



23: Wheel osf  
Scratched  
Over 50mm



24: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK