



VEHICLE INSPECTION REPORT

GF68OOW

Seat Arona 1.0 TSI 115 Xcellence Lux [EZ] 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	10/11/2018	Body Style	Hatchback	MOT Due	Expired
Year	2018	Keys	2	Gearbox	SEMI AUTO
Mileage	42,687 Miles Warranted	Service history	Yes	Gears	7
Fuel Type	Petrol	Service documents	Printout	Doors	5
Colour	BLUE	Last service date	31/10/2024		
VIN	VSSZZZKJZKR033050	Last service miles	38,962		

Last service 31/10/2024 @ 38962 miles (6 SERVICES 5 MAIN DEALER)

Tyres

NSF	BUDGET	5.0mm
NSR	TRIANGLE	6.0mm
OSF	BUDGET	5.0mm
OSR	ROADSTONE	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Over 50mm



3: Wheel nsr
Scratched
Over 50mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing osf
Chipped
1 To 5



6: Door osf
Chipped
1 To 5



7: Door osf
Chipped
Edge Chip



8: Door osr
Dented
Between 10mm + 30mm




9: Door osr
Chipped
Edge Chip



10: Door nsr
Chipped
1 To 5



11: Bonnet
Chipped
1 To 5



12: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK