

VEHICLE INSPECTION REPORT

RK22LBG

Audi A6 40 TFSI Sport 4dr S Tronic

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 2

Details

Reg. date	04/03/2022
Year	2022
Mileage	19,774 Miles Warranted
Fuel Type	Petrol
Colour	BLACK
VIN	WAUZZZ22NN012667

Body Style	Saloon
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	2
Last service date	22/12/2025

MOT Due	21/12/2026
Gearbox	SEMI AUTO
Gears	7
Doors	4

£65 ADDITIONAL FEE

Last service 22/12/2025 mileage recorded incorrectly- 2 main dealer services. Print

Tyres


NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Cruise control
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Up To 50mm

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Dented
Over 2 UpTo 10mm

No Image

No Image

7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Chipped
1 To 5

No Image

9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



11: Wheel nsr
Scratched
Up To 50mm



12: Bumper Rear
Chipped
Multiple Chips



13: Bumper Rear
Scratched
Over 25mm Not Thru Paint

14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Door osf
Chipped
1 To 5



16: Door osf
Dented
Over 2 UpTo 10mm

No Image

17: Wing osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK