

VEHICLE INSPECTION REPORT

VX69SHZ

Porsche Macan S 5dr PDK

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 3

Details

Reg. date	24/09/2019
Year	2019
Mileage	39,188 Miles Warranted
Fuel Type	Petrol
Colour	GREY
VIN	WP1ZZZ95ZLLB33303

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	2
Last service date	25/09/2023

Last service miles	17,568
MOT Due	15/12/2026
Gearbox	SEMI AUTO
Gears	7

£65 ADDITIONAL FEE.

Last service 25/09/2023 at 17,568 miles- 2 main dealer services. Book

Tyres


NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- PAS
- Audio remote control
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Screen Front
Cracked
Replace



2: Bonnet
Dented
Over 30mm



3: Bumper Front
Chipped
1 To 5



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
Up To 25mm Thru Paint



6: Door nsr
Dented
With Paint Damage



7: Bumper Rear
Scratched
Up To 25mm Thru Paint



8: Qtr Panel osr
Chipped
1 To 5



9: Door osr
Dented
Between 10mm + 30mm



10: Door osf
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK