



VEHICLE INSPECTION REPORT

RY24NZX

Lexus LBX 1.5 Premium Plus 5dr E-CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/08/2024	Body Style	Hatchback	Last service miles	1,623
Year	2024	Keys	2	Gearbox	CVT
Mileage	3,153 Miles Warranted	Service history	Yes	Gears	1
Fuel Type	Hybrid Electric	Service documents	Printout	Doors	5
Colour	RED	Number of stamps	1		
VIN	JTHAAAAE301017997	Last service date	20/08/2025		

Last service 20/08/2025 at 1623 miles- 1 main dealer service. Print

Tyres

NSF	YOKOHAMA	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	YOKOHAMA	6.0mm
OSR	YOKOHAMA	5.0mm
Spare		

Features


- Bluetooth connection
 - Navigation system
 - Rear wiper
 - Electric door mirrors
 - Front electric windows
 - Rear headrests
 - 3x3 point rear seat belts
 - Isofix child seat anchor points
 - Central locking
- Cruise control
 - Park assist camera
 - Steering wheel mounted controls
 - Air conditioning
 - Front head restraints
 - Steering wheel rake adjustment
 - ABS
 - Passenger airbag
 - Remote central locking
- Front parking sensor
 - PAS
 - Digital radio
 - Folding rear seats
 - Height adjustable drivers seat
 - Steering wheel reach adjustment
 - Drivers airbag
 - Side airbags
 - Leather seat trim
- Heated front seat
 - Rear parking sensor
 - Body coloured bumpers
 - Front armrest
 - Rear electric windows
 - Metallic Paint
 - ESP
 - Tyre pressure monitor
 - Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Front
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK