

VEHICLE INSPECTION REPORT

GY16BTM

Toyota Yaris 1.33 VVT-i Icon 5dr

Inspection	Vehicle	nama	
Serious Damage?	VAT	Margin	GRADE
	V5	Present	3

Details

Reg. date	31/03/2016	Body Style	Hatchback	Last service miles	43,785
Year	2016	Keys	2	MOT Due	30/03/2026
Mileage	63,239 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	RED	Number of stamps	5	Doors	5
VIN	VNKKJ3D310A351173	Last service date	12/03/2022		

Last Service - 12.03.2022 at 43785 miles (5 services)

Tyres

NSF	HIFLY	4.0mm
NSR	DOUBLESTAR	5.0mm
OSF	HIFLY	4.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Cloth seat trim
- Park assist camera
- Digital radio
- Space saver spare wheel
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Body coloured bumpers
- Air conditioning
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bonnet
Chipped
1 To 5



3: Wheel nsf
Scratched
Up To 50mm




4: Wing nsf
Scratched
UpTo 25mm Thru Paint




5: Door nsf
Dented
Between 10mm + 30mm




6: Door nsf
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Scratched
25 to 100mm Thru Paint




9: Door osf
Chipped
Edge Chip



10: Door osf
Chipped
Edge Chip



11: Screen Front
Chipped
UpTo 10mm



12: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK