

VEHICLE INSPECTION REPORT

FR62EFO

Audi A3 1.6 TDI Sport 5dr

Inspection	Vehicle		GRADE 5
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	29/01/2013	Body Style	Hatchback	MOT Due	23/08/2026
Year	2013	Keys	2	Gearbox	MANUAL
Mileage	109,863 Miles Warranted	Service history	Yes	Gears	5
Fuel Type	Diesel	Number of stamps	2	Doors	5
Colour	BLUE	Last service date	23/08/2016		
VIN	WAUZZZ8P6DA053320	Last service miles	51,937		

£100 ADDITIONAL FEE.

Last service 23/08/2016 at 51,937 miles- 2 main dealer services confirmed by Audi, Crawley Flywheel vibrates when pulling away
Rear brakes rubbing and pulling
Rear wiper does not work

Tyres



NSF	GOODYEAR	5.0mm
NSR	FULDA	5.0mm
OSF	GOODYEAR	5.0mm
OSR	FULDA	5.0mm
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wing nsf
Chipped
1 To 5



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Over 30mm



6: Sill ns
Dented
Over 30mm



7: Door nsr
Dented
Over 30mm



8: Qtr Panel nsr
Dented
Over 30mm



9: Bumper Rear
Dented
With Paint Damage



10: Tailgate
Poor Previous Repair
Paint Flake



11: Qtr Panel osr
Rusted
Over 5mm



12: Door osr
Scratched
UpTo 25mm Thru Paint



13: Door osf
Chipped
Edge Chip



14: Wheel osf
Scratched
Up To 50mm



15: Wing osf
Chipped
1 To 5



16: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK