

## VEHICLE INSPECTION REPORT

GV17FVE

### Nissan X-Trail 1.6 DiG-T Tekna 5dr [7 Seat]

Inspection	Vehicle		GRADE 4
Serious Damage?	VAT	Margin	
No	V5	Present	

#### Details

Reg. date	27/06/2017	Body Style	Estate	Last service miles	26,281
Year	2017	Keys	2	MOT Due	25/10/2026
Mileage	109,431 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	2		
VIN	JN1JDAT32U0005460	Last service date	12/05/2015		

Last Service - 12.05.2015 at 26281 miles (2 services)

#### Tyres



NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belt
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Dented  
Between 10mm + 30mm



2: Bonnet  
Scratched  
Over 25mm Thru Paint



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint



4: Wing nsf  
Scratched  
UpTo 25mm Thru Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm



9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



10: Tailgate  
Scratched  
UpTo 25mm Thru Paint



11: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



12: Wheel osr  
Scratched  
Over 50mm



13: Door osr  
Dented  
Over 30mm



14: Door nsf  
Scratched  
Over 25mm Thru Paint



15: Wheel osf  
Scratched  
Over 50mm



16: Wing osf  
Chipped  
1 To 5

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		