

VEHICLE INSPECTION REPORT

GV64JCX

Ford Ecosport 1.0 EcoBoost Titanium 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 2

Details

Reg. date	30/01/2015
Year	2015
Mileage	64,770 Miles Warranted
Fuel Type	Petrol
Colour	SILVER
VIN	WF0BXXMRKBEP19665

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	1
Last service date	25/01/2022

Last service miles	45,172
MOT Due	13/09/2026
Gearbox	MANUAL
Gears	5
Doors	5

£65 ADDITIONAL FEE.

Last service 25/01/2022 at 45,172 miles- 1 service. Print Intermittent Noisy engine

Tyres

NSF	BUDGET	5.0mm
NSR	GOODYEAR	5.0mm
OSF	BUDGET	5.0mm
OSR	HANKOOK	5.0mm
Spare		OK

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Central locking
- Telephone
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Door osf
Scratched
UpTo 25mm Thru Paint




2: Door osf
Chipped
Edge Chip



3: Door osr
Chipped
Edge Chip




4: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



5: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



6: Door nsr
Dented
2 Or Less UpTo 10mm



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Bonnet
Dented
2 Or Less UpTo 10mm



9: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK