

VEHICLE INSPECTION REPORT

LJ16VLC

Ford Ranger Pick Up Double Cab XLT 2.2 TDCi

Inspection

Serious Damage? No

Vehicle

Plus VAT

VAT V5

nama
GRADE 4

Details

Reg. date	04/08/2016
Year	2016
Mileage	113,874 Miles Warranted
Fuel Type	Diesel

Colour	GREY
VIN	6FPPXXMJ2PGB41164
Body Style	Pick-up
Keys	1

MOT Due	07/02/2026
Gearbox	MANUAL
Gears	6


Tyres



NSF	GENERAL TIRE	7.0mm
NSR	PIRELLI	5.0mm
OSF	GENERAL TIRE	5.0mm
OSR	GENERAL TIRE	7.0mm
Spare		

Features


- Bluetooth connection
- Air conditioning
- Drivers airbag
- Cruise control
- Front electric windows
- Passenger airbag
- Park assist camera
- Rear electric windows
- Central locking
- Radio/CD
- Metallic Paint
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint

4: Wheel nsf
Scratched
Up To 50mm



5: Door nsf
Chipped
Multiple Chips

6: Door nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Wheel nsr
Scratched
Up To 50mm



9: Boot Lid
Dented
Over 30mm



10: Qtr Panel osr
Chipped
Multiple Chips




11: Wheel osr
Scratched
Up To 50mm



12: Door osr
Dented
With Paint Damage



13: Door osf
Dented
Over 2 UpTo 10mm



14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Wing osf
Chipped
1 To 5



16: Wheel osf
Scratched
Up To 50mm



17: Carpets Front
Torn
Between 3mm + 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK