

VEHICLE INSPECTION REPORT

WN11EYK

Land Rover Range Rover 4.4 TDV8 Vogue 4dr Auto

| Inspection | Vehicle | nama GRADE 4 |
|-----------------|---------|-----------------|
| Serious Damage? | VAT | Margin |
| No | V5 | Photocopy |

Details

| | | | | | |
|-----------|----------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 09/06/2011 | Body Style | Estate | Last service miles | 118,451 |
| Year | 2011 | Keys | 2 | MOT Due | 23/06/2026 |
| Mileage | 133,190 Miles Warranted | Service history | Yes | Gearbox | AUTOMATIC |
| Fuel Type | Diesel | Service documents | Service Book | Gears | 8 |
| Colour | GOLD | Number of stamps | 12 | | |
| VIN | SALLMAMJ3BA348208 | Last service date | 11/09/2024 | | |

£65 ADDITIONAL FEE

Last service 11/09/2024 at 118,451 miles- 12 services (7 main dealer) Book and print
Copy of V5 Osr window does not open

Tyres

| | | |
|-------|---------|-------|
| NSF | PIRELLI | 2.0mm |
| NSR | PIRELLI | 3.0mm |
| OSF | PIRELLI | 2.0mm |
| OSR | PIRELLI | 2.0mm |
| Spare | | |

Features


| | | | |
|--|---|--|--|
| <ul style="list-style-type: none"> Bluetooth connection Park assist camera Audio remote control Opening panoramic glass roof Front electric windows Rear headrests Drivers airbag Traction control Alloy wheels | <ul style="list-style-type: none"> Cruise control PAS Body coloured bumpers Air conditioning Front head restraints Metallic Paint Isofix child seat anchor points Central locking | <ul style="list-style-type: none"> Heated front seat Rear wiper Electric door mirrors Climate control Height adjustable drivers seat 3x3 point rear seat belts Passenger airbag Remote central locking | <ul style="list-style-type: none"> Navigation system Steering wheel mounted controls Electric sunroof Front armrest Rear electric windows ABS Side airbags Leather seat trim |
|--|---|--|--|

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wing nsf
Chipped
1 To 5



7: Door nsf
Chipped
1 To 5

4: Wheel nsf
Scratched
Over 50mm

No Image

6: Wing nsf
Scratched
Over 25mm Not Thru Paint

No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Dented
With Paint Damage



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Chipped
Multiple Chips



13: Bumper Rear
Scratched
Over 25mm Not Thru Paint



14: Boot Lid
Dented
Over 2 UpTo 10mm



15: Qtr Panel osr
Chipped
1 To 5

No Image

16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Wheel osr
Corroded
Light

18: Door osr
Rusted
UpTo 5mm



19: Door osf
Chipped
1 To 5

No Image

20: Door osf
Scratched
Over 25mm Not Thru Paint



21: Wing osf
Chipped
1 To 5



22: Wheel osf
Scratched
Over 50mm



23: Screen Front
Chipped
UpTo 10mm



24: Roof
Dented
2 Or Less UpTo 10mm



25: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|-------|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Roof / sunroof | OK | Radio | OK |
| Windows | Fault | Steering | OK |
| Sat nav | OK | | |