

VEHICLE INSPECTION REPORT

LL68ZDC

Audi Q5 2.0 TDI Quattro S Line 5dr S Tronic

| Inspection | Vehicle | | GRADE nama 3 |
|-----------------|---------|---------|--------------------|
| Serious Damage? | VAT | Margin | |
| No | V5 | Present | |

Details

| | | | | | |
|-----------|---------------------------|-------------------|------------|--------------------|------------|
| Reg. date | 11/01/2019 | Body Style | Estate | Last service miles | 53,541 |
| Year | 2019 | Keys | 2 | MOT Due | 13/11/2026 |
| Mileage | 55,677 Miles Warranted | Service history | Yes | Gearbox | SEMI AUTO |
| Fuel Type | Diesel | Service documents | Printout | Gears | 7 |
| Colour | BLUE | Number of stamps | 6 | | |
| VIN | WAUZZZFY2J2157742 | Last service date | 05/11/2025 | | |

£65 ADDITIONAL FEE. Last service 05/11/2025 at 53541 miles (6 services).

Tyres


| | | |
|-------|-------------|-------|
| NSF | BRIDGESTONE | 4.0mm |
| NSR | BRIDGESTONE | 4.0mm |
| OSF | BRIDGESTONE | 4.0mm |
| OSR | BRIDGESTONE | 3.0mm |
| Spare | | |

Features


| | | | |
|----------------------------------|-----------------------------|--------------------------|-----------------------------------|
| • Bluetooth connection | • Cruise control | • Front parking sensor | • Navigation system |
| • PAS | • Rear parking sensor | • Rear wiper | • Steering wheel mounted controls |
| • Audio remote control | • Body coloured bumpers | • Electric door mirrors | • Air conditioning |
| • Climate control | • Front armrest | • Front electric windows | • Front head restraints |
| • Height adjustable drivers seat | • Rear electric windows | • Rear headrests | • Metallic Paint |
| • 3x3 point rear seat belts | • ABS | • Drivers airbag | • Isofix child seat anchor points |
| • Passenger airbag | • Side airbags | • Traction control | • Central locking |
| • Remote central locking | • Partial leather seat trim | • Alloy wheels | |

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint


No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wheel nsf
Scratched
Over 50mm

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Poor Previous Repair
Poor Paint



7: Door nsr
Poor Previous Repair
Poor Paint

8: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm




11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Dented
Over 2 UpTo 10mm



14: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Chipped
1 To 5



17: Door osf
Scratched
Over 25mm Thru Paint



18: Wing osf
Dented
Between 10mm + 30mm



19: Screen Front
Chipped
UpTo 10mm

Interior

| | |
|-------------------------|---------|
| Carpet Condition | Average |
| Seat Condition | Average |

| | |
|-----------------------------|---------|
| Upholstery Condition | Average |
| Odour | No |

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |