

## VEHICLE INSPECTION REPORT

SG72XCT

### BMW 3 Series 320i M Sport 5dr Step Auto

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 2

#### Details

Reg. date	28/10/2022
Year	2022
Mileage	27,331 Miles Warranted
Fuel Type	Petrol
Colour	GREY
VIN	WBA22FY080FN65343

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Electronic & Paper
Number of stamps	3
Last service date	25/09/2025

Last service miles	25,523
MOT Due	28/04/2026
Gearbox	AUTOMATIC
Gears	8

Last service 25/09/2025 at 25,523 miles- 3 main dealer services. Recorded on on- board system Bonnet out of line

#### Tyres



NSF	PIRELLI	3.0mm
NSR	BRIDGESTONE	3.0mm
OSF	PIRELLI	3.0mm
OSR	BRIDGESTONE	3.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Central locking
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Leather seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels

## Photos





## Condition Check



## Damage Photos




1: Bumper Rear  
Chipped  
Multiple Chips

No Image

2: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

# No Image


3: Boot Lid  
Scratched  
Over 25mm Not Thru Paint




4: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



5: Wheel osr  
Scratched  
Up To 50mm



6: Door osr  
Dented  
Over 2 UpTo 10mm



7: Door osf  
Dented  
2 Or Less UpTo 10mm




8: Wheel osf  
Scratched  
Up To 50mm



9: Bonnet  
Chipped  
1 To 5



10: Bumper Front  
Chipped  
Multiple Chips



11: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



12: Wheel nsf  
Scratched  
Up To 50mm



13: Wing nsf  
Chipped  
1 To 5



14: Door nsf  
Dented  
2 Or Less UpTo 10mm



15: Door nsr  
Chipped  
1 To 5



16: Wheel nsr  
Scratched  
Up To 50mm



17: Qtr Panel nsr  
Chipped  
1 To 5

## Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK