

## VEHICLE INSPECTION REPORT

GV73HWR

### Mini Hatchback 1.5 Cooper Exclusive 3dr Auto

#### Inspection

Serious Damage? No

#### Vehicle

|     |         |
|-----|---------|
| VAT | Margin  |
| V5  | Present |

nama  
GRADE  
2

#### Details

|           |                           |
|-----------|---------------------------|
| Reg. date | 31/01/2024                |
| Year      | 2024                      |
| Mileage   | 10,247 Miles<br>Warranted |
| Fuel Type | Petrol                    |
| Colour    | RED                       |

|                 |                   |
|-----------------|-------------------|
| VIN             | WMW32DH0202V91484 |
| Body Style      | Hatchback         |
| Keys            | 2                 |
| Service history | None              |
| MOT Due         | 30/01/2027        |

|         |           |
|---------|-----------|
| Gearbox | AUTOMATIC |
| Gears   | 7         |
| Doors   | 3         |

PDI Only First service due

#### Tyres


|       |         |       |
|-------|---------|-------|
| NSF   | BUDGET  | 5.0mm |
| NSR   | PIRELLI | 5.0mm |
| OSF   | PIRELLI | 5.0mm |
| OSR   | PIRELLI | 5.0mm |
| Spare |         |       |

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Opening panoramic glass roof
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Chipped  
1 To 5



3: Wheel nsf  
Scratched  
Over 50mm



4: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



5: Door osf  
Chipped  
Edge Chip



6: Wheel osf  
Scratched  
Over 50mm

## Interior

|                  |         |
|------------------|---------|
| Carpet Condition | Average |
| Seat Condition   | Average |

|                      |         |
|----------------------|---------|
| Upholstery Condition | Average |
| Odour                | No      |

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

|                |    |  |    |
|----------------|----|--|----|
| Engine Runs    | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes         | OK | Gearbox Static Gear Selection (engine running) | OK |
| Turbo Boosting | OK | No Excessive Smoking                           | OK |
| Parking Brake  | OK |  |    |

|                          |    |                                     |    |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated    | OK | Oil warning light illuminated       | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated    | OK |                                     |    |
| Roof / sunroof           | OK | Radio                               | OK |
| Windows                  | OK |                                     |    |
| Sat nav                  | OK |                                     |    |