

VEHICLE INSPECTION REPORT

GN66VGE

Ford Focus 1.5 TDCi 120 Titanium 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	08/09/2016
Year	2016
Mileage	75,350 Miles Warranted
Fuel Type	Diesel
Colour	BLUE
VIN	WF05XXGCC5GK28019

Body Style	Hatchback
Keys	2
Service history	Yes
Number of stamps	8
Last service date	02/03/2024
Last service miles	60,512

MOT Due	07/09/2026
Gearbox	MANUAL
Gears	6
Doors	5

£65 ADDITIONAL FEE

Last service 02/03/2024 at 60,512 miles- 8 main dealer services confirmed by Invicta MG, Canterbury

Tyres

NSF	HANKOOK	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	HANKOOK	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Full size spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm



4: Door nsf
Dented
Over 30mm



5: Aperture Seal nsr
Broken
Replace



6: Qtr Panel nsr
Dented
With Paint Damage



7: Bumper Rear
Chipped
1 To 5



8: Qtr Panel osr
Scratched
Rusted



9: Door osr
Chipped
Edge Chip



10: Wing osf
Poor Previous Repair
Poor Colour

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK