

VEHICLE INSPECTION REPORT

GC18TNK

Skoda Fabia 1.0 MPI 60 S Plus 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 3

Details

Reg. date	27/07/2018
Year	2018
Mileage	52,528 Miles Warranted
Fuel Type	Petrol
Colour	WHITE
VIN	TMBFA6NJ0JZ128215

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	6
Last service date	14/07/2025

Last service miles	48,730
MOT Due	26/07/2026
Gearbox	MANUAL
Gears	5
Doors	5

£65 ADDITIONAL FEE. Last service 14/07/2025 at 48730 miles (6 services (2 main dealer)).


Tyres


NSF	GOODYEAR	5.0mm
NSR	FULDA	5.0mm
OSF	GOODYEAR	5.0mm
OSR	ROADSTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Rear wiper
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- ESP
- Central locking
- Digital radio
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsr
Scratched
UpTo 25mm Thru Paint



5: Qtr Panel nsr
Dented
Between 10mm + 30mm



6: Bumper Rear
Scratched
25 to 100mm Thru Paint




7: Door osr
Chipped
Edge Chip



8: Door osf
Dented
Over 30mm



9: Wheel osf
Scratched
Over 50mm



10: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK