



VEHICLE INSPECTION REPORT

FN55FKZ

TRIGANO

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 12/02/2006

Year 2006

Mileage 48,623 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA24400007585928

Body Style Motor Caravan

Keys 2

Service history Yes

Service documents Printout

MOT Due 08/10/2026

£100 ADDITIONAL FEE

Last service 14/01/2025 at 45,230 miles- 1 service. Print Intermixed starting fault

Tyres

NSF BUDGET 4.0mm

NSR SUNNY 4.0mm

OSF HIFLY 4.0mm


OSR BUDGET 4.0mm



Spare

Features

- Radio/CD
- Front electric windows
- Central locking
- Partial leather seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Wing nsf
Poor Previous Repair
Poor Paint



3: Door nsf
Poor Previous Repair
Poor Paint



4: Sill Panel Trim ns
Broken
Replace



5: Door nsr
Poor Previous Repair
Paint Flake



6: Qtr Panel nsr
Poor Previous Repair
Poor Paint



7: Boot Lid
Dented
With Paint Damage



8: Qtr Panel osr
Dented
With Paint Damage



9: Door osr
Poor Previous Repair
Poor Paint



10: Sill Panel Trim os
Scratched (Painted)
Over 25mm Thru Paint



11: Door osf
Poor Previous Repair
Poor Paint



12: Wing osf
Poor Previous Repair
Poor Paint



13: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK