

VEHICLE INSPECTION REPORT

GN14NHD

Volkswagen Tiguan 2.0 TDi BlueMotion Tech Match 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 3

Details

Reg. date	01/03/2014
Year	2014
Mileage	105,970 Miles Warranted
Fuel Type	Diesel
Colour	BLACK
VIN	WVGZZZ5NZEW065124

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	10
Last service date	22/04/2024

Last service miles	91,861
MOT Due	27/04/2026
Gearbox	MANUAL
Gears	6

£65 ADDITIONAL FEE.

Last service 22/04/2024 at 91,861 miles- 10 services (4 main dealer) Book Bulb light on dash
Oil change and inspection due

Tyres




NSF	KUMHO	2.0mm
NSR	FULLRUN	3.0mm
OSF	KUMHO	2.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Radio/CD
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Chipped
Multiple Chips

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wheel nsf
Scratched
Up To 50mm




5: Wing nsf
Dented
Over 2 UpTo 10mm

No Image

6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Chipped
Multiple Chips



8: Door nsr
Chipped
1 To 5

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Chipped
1 To 5

No Image

12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image


14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Boot Lid
Dented
Over 2 UpTo 10mm

No Image

16: Boot Lid
Scratched
Over 25mm Not Thru Paint



17: Qtr Panel osr
Scratched
Over 25mm Thru Paint



18: Wheel osr
Scratched
Up To 50mm



19: Door osr
Chipped
Multiple Chips



20: Door osf
Dented
Over 2 UpTo 10mm

No Image

21: Door osf
Scratched
Over 25mm Not Thru Paint



22: Wing osf
Chipped
1 To 5

No Image

23: Wing osf
Scratched
Over 25mm Not Thru Paint



24: Wheel osf
Scratched
Up To 50mm



25: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		