

VEHICLE INSPECTION REPORT

GF58JZN

Smart Fortwo Cabrio Passion 2dr Auto

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	25/10/2008
Year	2008
Mileage	85,140 Miles Warranted
Fuel Type	Petrol
Colour	SILVER
VIN	WME4514312K190733

Body Style	Convertible
Keys	1
Service history	Yes
Service documents	Printout
Number of stamps	7
Last service date	26/03/2025

Last service miles	81,516
MOT Due	19/12/2026
Gearbox	AUTOMATIC
Gears	5

Last Service - 26.03.2025 at 81516 miles (7 services) EML light on
Car has been plugged in and detects o2 heater circuit bank 1 sensor 2
O2 circuit no activity detected bank 1 sensor 2
Exhaust blowing

Tyres



NSF	CONTINENTAL	5.0mm
NSR	YOKOHAMA	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	NANKANG	5.0mm
Spare		

Features


- Heated front seat
- PAS
- Radio/CD
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Front head restraints
- Metallic Paint
- ABS
- Drivers airbag
- Passenger airbag
- Central locking
- Remote central locking
- Leather seat trim
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsr
Scratched
Up To 50mm



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Wheel osr
Scratched
Over 50mm



8: Door osf
Chipped
Edge Chip



9: A Post os
Scratched
UpTo 25mm Thru Paint



10: Wheel osf
Scratched
Up To 50mm



11: A Post ns
Scratched
Rusted



12: Seat Base Cover nsf
Holed
Over 3mm



13: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK