

## VEHICLE INSPECTION REPORT

NU71VDJ

### Audi Q5 40 TDI Quattro Edition 1 5dr S Tronic

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Photocopy

nama  
GRADE 2

#### Details

Reg. date	30/10/2021
Year	2021
Mileage	60,998 Miles Warranted
Fuel Type	Diesel
Colour	BLUE
VIN	WAUZZZFY6M2141015

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	4
Last service date	07/08/2025

Last service miles	50,888
MOT Due	04/11/2026
Gearbox	SEMI AUTO
Gears	7

£65 ADDITIONAL FEE. COPY V5.

Last service 07/08/2025 at 50888 miles (4 main dealer services).

#### Tyres


NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	4.0mm
OSR	GOODYEAR	4.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- PAS
- Audio remote control
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5




2: Bumper Front  
Chipped  
Multiple Chips

# No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wing osf  
Chipped  
1 To 5



5: Door osf  
Dented  
2 Or Less UpTo 10mm

# No Image

6: Door osr  
Scratched  
Over 25mm Not Thru Paint



7: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm


8: Bumper Rear  
Chipped  
Multiple Chips

# No Image




9: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

10: Boot Lid  
Dented  
2 Or Less UpTo 10mm



11: Qtr Panel nsr  
Dented  
2 Or Less UpTo 10mm



12: Door nsr  
Dented  
2 Or Less UpTo 10mm



13: Door nsf  
Chipped  
1 To 5

# No Image

14: Door nsf  
Scratched  
Over 25mm Not Thru Paint



15: Wing nsf  
Chipped  
1 To 5



16: Wheel nsf  
Scratched  
Up To 50mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK