

## VEHICLE INSPECTION REPORT

GL22KFX

### Kia E-Niro 150kW 2 Long Range 64kWh 5dr Auto

Inspection	Vehicle		GRADE 2
Serious Damage?	VAT	Margin	
No	V5	Present	

#### Details

Reg. date	30/06/2022	Body Style	Estate	Last service miles	14,217
Year	2022	Keys	2	MOT Due	29/06/2026
Mileage	25,433 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Service Book	Gears	1
Colour	GREY	Number of stamps	2		
VIN	KNACB81GUN5155379	Last service date	22/05/2024		

Last Service - 22.05.2024 at 14217 miles (2 services) Type 2 and 3 pin charging cables

#### Tyres

NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	VREDESTEIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

## Features


• Bluetooth connection	• Cruise control	• Park assist camera	• PAS
• Rear parking sensor	• Rear wiper	• Steering wheel mounted controls	• Digital radio
• Body coloured bumpers	• Electric door mirrors	• Front fog lights	• Roof rails
• Air conditioning	• Folding rear seats	• Front armrest	• Front electric windows
• Front head restraints	• Height adjustable drivers seat	• Rear electric windows	• Rear headrests
• Steering wheel rake adjustment	• Steering wheel reach adjustment	• Metallic Paint	• 3x3 point rear seat belts
• ABS	• Drivers airbag	• ESP	• Isofix child seat anchor points
• Passenger airbag	• Side airbags	• Central locking	• Remote central locking
• Partial leather seat trim	• Alloy wheels		

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
UpTo 25mm Thru Paint




3: Wing nsf  
Scratched  
Up To 25mm Thru Paint



4: Wheel nsf  
Scratched  
Up To 50mm



5: Door nsf  
Scratched  
Up To 25mm Thru Paint



6: Door nsr  
Dented  
Over 30mm



7: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



8: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



9: Door osr  
Scratched  
UpTo 25mm Thru Paint



10: Door osf  
Chipped  
Edge Chip

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK