

# VEHICLE INSPECTION REPORT

GU23HWB

## Toyota Yaris 1.5 Hybrid Excel 5dr CVT

### Inspection

Serious Damage? No

### Vehicle

VAT	VAT Qualifying
V5	Present

nama  
GRADE 3

### Details

Reg. date	27/04/2023
Year	2023
Mileage	68,962 Miles Warranted
Fuel Type	Hybrid Electric
Colour	GREY
VIN	VNKKBAC390A263457

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	5
Last service date	20/06/2025

Last service miles	60,500
Gearbox	CVT
Gears	1
Doors	5

Last service 20/06/2025 at 60,500 miles- 5 main dealer services. Book and print

### Tyres

NSF	NEXEN	5.0mm
NSR	HANKOOK	5.0mm
OSF	NEXEN	5.0mm
OSR	HANKOOK	5.0mm
Spare		

## Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Partial leather seat trim


## Photos





Eastbourne Car Auctions

## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



5: Wheel nsr  
Scratched  
Up To 50mm



6: Door osf  
Dented  
Over 30mm



7: Wing osf  
Chipped  
1 To 5



8: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK