

VEHICLE INSPECTION REPORT

GY59KHC

Toyota Yaris 1.33 VVT-i TR 5dr MMT [6]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	04/11/2009	Colour	RED	MOT Due	04/11/2025
Year	2009	VIN	VNKKH98360A079860	Gearbox	SEMI AUTO
Mileage	20,560 Miles Warranted	Body Style	Hatchback	Gears	6
Fuel Type	Petrol	Keys	2	Doors	5


Tyres

NSF	BUDGET	6.0mm
NSR	DUNLOP	6.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	6.0mm
Spare	BUDGET	OK

Features


- Rear wiper
- Air conditioning
- ABS
- Remote central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Alloy wheels
- Electric door mirrors
- Solid Paint
- Central locking

Photos





Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Up To 50mm



3: Wheel nsf
 Scratched
 Up To 50mm



4: Door Mirror Assy osf
 Scratched (Painted)
 Over 25mm Thru Paint



5: Other
 N/A
 N/A



6: Door osr
 Scratched
 UpTo 25mm Thru Paint



7: Other
 N/A
 N/A



8: Other
 N/A
 N/A




9: Other
N/A
N/A



10: Sill ns
Scratched
UpTo 25mm Thru Paint



11: Roof
Dented
Over 2 UpTo 10mm



12: Door nsf
Dented
Over 2 UpTo 10mm



13: C Post ns
Dented
Between 10mm + 30mm



14: A Post os
Poor Previous Repair
Paint Flake

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK