

## VEHICLE INSPECTION REPORT

GF66OLC

### Skoda Fabia 1.2 TSI Monte Carlo 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 1

#### Details

Reg. date	22/12/2016
Year	2016
Mileage	33,530 Miles Warranted
Fuel Type	Petrol
Colour	BLUE
VIN	TMBFN6NJ5HZ080550

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	8
Last service date	16/01/2026

Last service miles	33,397
MOT Due	22/12/2026
Gearbox	MANUAL
Gears	6
Doors	5

#### £65 ADDITIONAL FEE

Last service 16/01/2026 at 33,397 miles- 8 services (4 main dealers) Print

#### Tyres

NSF	FALKEN	4.0mm
NSR	FALKEN	4.0mm
OSF	FALKEN	4.0mm
OSR	FALKEN	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5

2: Bumper Front  
Chipped  
Multiple Chips


# No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Up To 50mm

# No Image



5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

6: Door nsf  
Dented  
Over 2 UpTo 10mm



7: Door nsr  
Dented  
2 Or Less UpTo 10mm

# No Image

8: Door nsr  
Scratched  
Over 25mm Not Thru Paint

# No Image

9: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint




10: Bumper Rear  
Chipped  
Multiple Chips

# No Image

11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint




12: Boot Lid  
Chipped  
1 To 5




13: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm




14: Wheel osr  
Scratched  
Up To 50mm




15: Door osr  
Chipped  
1 To 5



16: Door osf  
Chipped  
1 To 5



17: Wing osf  
Chipped  
1 To 5



18: Screen Front  
Chipped  
UpTo 10mm



19: Wheel osf  
Scratched  
Up To 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK